


ENGINE REBUILDING - 1922 LINCOLN V-8



Arrival Photo - not run in 32 years



Torn down



Aluminum Crankcase




Steam Cleaning



New Bearings Ready to Install




Transmission & Covers Ready to Install



New Timing Chain




New pistons, rings, rod bearings



Cylinders, Flywheel mounted



Fitting Rods to Crankshaft




Check timing on cam



Rear View with Headers



Rebuilt Carburetor



On stand, ready for car



Installation



In Place